



Fleet Support Conference

Propeller Drive Adapter

Corrosion Improvement

Tom Whelan
Code R51

05-07OCT04

Fleet Support Conference

Propeller Drive Adapter

Corrosion Improvement

- Prop Drive Adapter Corrosion:





Fleet Support Conference

Propeller Drive Adapter

Corrosion Improvement

- P/N 6904005001, NIIN 9C 01-199-7749, \$119,423 each, throw-away item, long-lead item
- Start refurbishing similar to SLEP GFM 20 Critical Items, blast, prime and paint before corrosion gets too bad
- Recommend task to refurbish 4 from NSWC-PC ROS craft to start rotatable pool at ACUs
- Recommend task to fund Dowty for re-design for marine environment – similar to control module improvement.



Fleet Support Conference

Propeller Drive Adapter

Corrosion Improvement

- Points of Contact
 - Tom Whelan, NSWC-PC Code R51, (850) 235-5042,
thomas.whelan@navy.mil
 - Bob Adkins, NSWC-PC Code R51, (850) 234-4409
robert.a.adkins1@navy.mil